Proposal

McCook Office 512 Airport Road McCook, Nebraska 69001 (800) 892 3848 (308) 345-6670

ACCEPTANCE OF PROPOSAL

be made as outlined above.

Date of Acceptance:

and conditions are satisfactory and are hereby accepted. You are authorized to perform the work as specified. Payment will

FAX (308) 345-4389

Weathercraft Companies

FAX: (308) 532-4625

Roofing, Sheet Metal, Siding & Overhead Door Contractors 2401 East 8th Street, PO Box 1949 North Platte, Nebraska 69103-1949 Business Phone: (308) 534-3480 Toll Free: (800) 662-2981 Prepared By: Brett Schmidt (308) 340 6216

Proposal Submitted to:		Phone		ate
Dundy Co Schools		(308) 882-1865		12/9/2024
Street P.O. Box 586		Job Name Elementary School (South Wing)		
City, State and Zip Code		Job Location		
Benkelman NE 69021		400 West 9th Avenue , Benkelman NE 69021		nan NE 69021
Contact	e-mail	£	Job Phone	
Rich	4	Ifax	(308) 882-1865	
We hereby submit specifications and estimates for: South Wing Ballasted Roof Replacement				
A. Move and re-use existing ballast rock.				
B. Remove existing .060 mil. EPDM (rubber) membrane and dispose of at landfill.				
C. Inspect existing insulation for damage or deterioration. Replace if needed.				
D. Install new Holcim .060 mil EPDM Ballasted Roof System running rubber up high walls and sealing with termination				
bar and elastomeric sealant, and over perimeter roof edge and parapets, terminating with new Una-Clad Gravel Stop Metal.				
E. Furnish and install new curb flashings, cold vent boots, hot vent jacks, penetration pockets, and other accessories				
required to secure a water tight roof system.				
F. Detail any and all breach areas to secure a water tight roof. Clear site of project related debris and dispose of at landfill.				
This system to include a Fifteen (15) Year Warranty through Holcim / Elevate Co. and Weathercraft Companies				
covering membrane and labor. Warranty excludes damages resulting from vandalism and projectiles.				
South Wing Roof Replacement: \$53,963.00				
During the inspection performed on December 6th, 2024, the roof initially appeared to be in good condition, however upon				
closer inspection, the roof displayed significant pulling on the parapet walls as well as at penetrations andloss of monomers				
which keeps the rubber membrane supple. To avoid emergency issues we recommend a replacement in the near future.				
Price does not reflect any applicable taxes.				
₩ε ৠτοροse hereby to furnish material and labor complete in accordance with above specifications, for the sum of:				
Fifty-Three-Thousand-Nine-Hundred-Sixty-Three Dollars and no .00/100 dollars (\$ 53,963.00)				
Payment to be made as follows:				
Due upon Completion All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any				
alteration or deviation from above specifications involving extra costs will be executed only upon written orders and will become an extra				
charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Owner to carry fire, tornado and other necessary insurance.				
Authorized 1		This proposal may be		
Signature	Clev	withdrawn by us if not acc	cepted within	

The above prices

Signature

